

SEARCHED

| Class | Sub. | Date | Exmr. |
|---------|--------------------------------------|---------|-------|
| 382 | 150 145, 147 149 203 286 | 8/14/03 | VMK |
| 348 | 126 | | |
| 356 | 600 614 625 | | |
| 438 | 7 612, 613 | | |
| 257 | 737 738 | | |
| Updated | Above | 2/9/04 | VMK |
| Updated | Above | 5/24/04 | VMK |

SEARCH NOTES (INCLUDING SEARCH STRATEGY)

| | Date | Exmr. |
|---|---------|-------|
| EAST Search See attached | 8/14/03 | VMK |
| Inventorship Assignee | 8/14/03 | VMK |
| IEEE Search Keywords: coining bump inspect top port planar area reflowing flip chip | 8/14/03 | VMK |
| Google Search see attached | 2/9/04 | VMK |
| IEEE Search see attached | 2/9/04 | VMK |
| Inventorship Search see attached | 2/9/04 | VMK |

INTERFERENCE SEARCHED

| Class | Sub. | Date | Exmr. |
|-------|------|------|-------|
| | | | |

BEST AVAILABLE COPY